



A x4
18mm MDF
Holes drilled at 9, 15, 25mm as indicated. 25mm drilled to accept casters.
Holes drilled on all four edges Ø9mm dia. to a depth of 100mm. Velcro attached where indicated.




15mm M15 pan-headed screws x16

D x2
15mm MDF
Holes drilled at 9mm as indicated.




velcro hinges (hooks)
450mm hinges for C in con.3
400mm hinges for E/F as indicated in con.4.


velcro hinges (loops)
24m approx
Self-adhesive 'loops' to be applied to all elements where indicated on drawings. Tape to be 40mm wide.




brackets for config. 4
x8
Steel supports, with 15mm studs where indicated.




B x4
15mm MDF
Holes drilled at 9mm into edges and 15mm on surface. Velcro attached where indicated, including one side face.




E x1
15mm MDF
Velcro attached as indicated.



supports for config. 3
x4
Welded steel supports
15mm holes drilled where indicated.



C x4
15mm MDF
Holes drilled at 9mm into edges and 15mm on surface. Velcro attached where indicated.




cutting pattern for tablecloth
holes to accept steel supports where indicated.



casters to fit piece A
x16

steel connecting dowels
x24


Drawing scale 1:25@A4.
Recommended printing scale for construction 1:1
calibrating scale from below.




plans for home conjuring unit



1
01




door open



door closed

2
01





part requirements


- 4 of piece A
- 4 of piece B
- 4 of piece C
- 2 of piece D
- 16 casters
- 21 steel connecting dowels
- 4 velcro hinges

configuration 1


bedroom wardrobe for spontaneous appearances




1
02




2
02



3
02



4
02




part requirements


- 4 of piece A
- 4 of piece B
- 4 of piece C
- 2 of piece D
- 16 casters
- 21 steel connecting dowels
- 4 velcro hinges

configuration 2


storage chest for splitting in two





1
03




2
03



3
03



4
03





5
03

part requirements

- 4 of piece A
- 2 of piece B
- 4 of piece C
- 10 steel connecting dowels
- 2 velcro hinges
- 4 steel supports
- 1 tablecloth
- 16 casters
- 16 screws

configuration 3

trestle table for floating on air



part requirements

- 4 of piece A
- 4 of piece B
- 3 of piece C
- 1 of piece E
- 1 of piece F
- 8 steel connecting dowels
- 10 velcro hinges
- 8 steel brackets
- 16 casters (optional)

configuration 4

nest tables for quick and easy escapes